
MARCH - 2015

**Ransburg** 

## DEUCE CART PACKAGE



**MODEL: 79297** 

**IMPORTANT:** Before using this equipment, carefully read SAFETY PRECAUTIONS, starting on page 1, and all instructions in this manual. Keep this Service Manual for future reference.

Service Manual Price: \$50.00 (U.S.)

**NOTE:** This manual has been changed from revision **SI-04-02.7** to revision **SI-04-02.8**. Reasons for this change are noted under "Manual Change Summary" on page 15 of this manual.

# **CONTENTS**

	PAGE
SAFETY:	1-5
SAFETY PRECAUTIONSHAZARDS / SAFEGUARDS	
INTRODUCTION:	6
DESCRIPTION79297 DEUCE CART PACKAGE OPTIONS	6 6
INSTALLATION:	7
POWER SUPPLY MOUNTING INSTRUCTIONS:MOUNTING POWER SUPPLY TO CART - DIAGRAM	
OPERATION:	8
INSTRUCTIONS:	8
PARTS IDENTIFICATION:	9-13
80002 CART ASSEMBLY 80002 CART ASSEMBLY - PARTS LIST 80001 AIR COMPRESSOR ASSEMBLY - PARTS LIST 79281 PRESSURE POT ASSEMBLY 79281 PRESSURE POT ASSEMBLY - PARTS LIST	10 11 12
WARRANTY POLICIES:	14
WARRANTY	14

## **SAFETY**

## SAFETY PRECAUTIONS

Before operating, maintaining or servicing any Ransburg electrostatic coating system, read and understand all of the technical and safety literature for your Ransburg products. This manual contains information that is important for you to know and understand. This information relates to USER SAFETY and PREVENTING EQUIPMENT PROBLEMS. To help you recognize this information, we use the following symbols. Please pay particular attention to these sections.

A WARNING! states information to alert you to a situation that might cause serious injury if instructions are not followed.

A CAUTION! states information that tells how to prevent damage to equipment or how to avoid a situation that might cause minor injury.

A NOTE is information relevant to the procedure in progress.

While this manual lists standard specifications and service procedures, some minor deviations may be found between this literature and your equipment. Differences in local codes and plant requirements, material delivery requirements, etc., make such variations inevitable. Compare this manual with your system installation drawings and appropriate Ransburg equipment manuals to reconcile such differences.

Careful study and continued use of this manual will provide a better understanding of the equipment and process, resulting in more efficient operation, longer trouble-free service and faster, easier troubleshooting. If you do not have the manuals and safety literature for your Ransburg system, contact your local Ransburg representative or Ransburg.

## **↑** WARNING

- ➤ The user **MUST** read and be familiar with the Safety Section in this manual and the Ransburg safety literature therein identified.
- This manual MUST be read and thoroughly understood by ALL personnel who operate, clean or maintain this equipment! Special care should be taken to ensure that the WARNINGS and safety requirements for operating and servicing the equipment are followed. The user should be aware of and adhere to ALL local building and fire codes and ordinances as well as NFPA-33 SAFETY STANDARD, LATEST EDITION, prior to installing, operating, and/or servicing this equipment.

## **★** WARNING

➤ The hazards shown on the following pages may occur during the normal use of this equipment. Please read the hazard chart beginning on page 2.

#### **AREA HAZARD SAFEGUARDS** Tells where hazards Tells what the hazard is. Tells how to avoid the hazard. may occur. **Spray Area Fire Hazard** Fire extinguishing equipment must be present Improper or inadequate in the spray area and tested periodically. operation and maintenance procedures Spray areas must be kept clean to prevent the will cause a fire hazard. accumulation of combustible residues. Protection against inadvertent Smoking must never be allowed in the spray area. arcing that is capable of The high voltage supplied to the atomizer must causing fire or explosion is lost be turned off prior to cleaning, flushing if any safety interlocks are or maintenance. disabled during operation. Frequent Power Supply or When using solvents for cleaning: Controller shutdown indicates Those used for equipment flushing should a problem in the system have flash points equal to or higher than requiring correction. those of the coating material. • The flash point of the cleaning solvent shall be at least 15° C (27° F) above the ambient temperature. Otherwise, the cleaning process must be carried out in an area with forced air ventilation. It is the end users responsibility to insure this condition is met. Spray booth ventilation must be kept at the rates required by NFPA-33, OSHA, country, and local codes. In addition, ventilation must be maintained during cleaning operations using flammable or combustible solvents. Electrostatic arcing must be prevented. Safe sparking distance must be maintained between the parts being coated and the applicator. A distance of 1 inch for every 10KV of output voltage is required at all times. Test only in areas free of combustible material. Testing may require high voltage to be on, but only as instructed. Non-factory replacement parts or unauthorized equipment modifications may cause fire or injury. If used, the key switch bypass is intended for use only during setup operations. Production should never be done with safety interlocks disabled. Never use equipment intended for use in waterborne installations to spray solvent based materials. The paint process and equipment should be set up and operated in accordance with NFPA-33, NEC, OSHA, local, country, and European Health and Safety Norms.

AREA Tells where hazards may occur.	HAZARD Tells what the hazard is.	SAFEGUARDS Tells how to avoid the hazard.
Spray Area	Explosion Hazard	
Spray Area	Improper or inadequate operation and maintenance procedures will cause a fire hazard.  Protection against inadvertent arcing that is capable of causing fire or explosion is lost if any safety interlocks are disabled during operation.  Frequent Power Supply or Controller shutdown indicates a problem in the system requiring correction.	Electrostatic arcing must be prevented. Safe sparking distance must be maintained between the parts being coated and the applicator. A distance of 1 inch for every 10KV of output voltage is required at all times.  Unless specifically approved for use in hazardous locations, all electrical equipment must be located outside Class I or II, Division 1 or 2 hazardous areas, in accordance with NFPA-33.  Test only in areas free of flammable or combustible materials.  The current overload sensitivity (if equipped) MUST be set as described in the corresponding section of the equipment manual. Protection against inadvertent arcing that is capable of causing fire or explosion is lost if the current overload sensitivity is not properly set. Frequent power supply shutdown indicates a problem in the system which requires correction.  Always turn the control panel power off prior to flushing, cleaning, or working on spray system equipment.  Before turning high voltage on, make sure no objects are within the safe sparking distance.  Ensure that the control panel is interlocked with the ventilation system and conveyor in accordance with NFPA-33, EN 50176.  Have fire extinguishing equipment readily available and tested periodically.
General Use and Maintenance	Improper operation or maintenance may create a hazard.  Personnel must be properly trained in the use of this equipment.	Personnel must be given training in accordance with the requirements of NFPA-33, EN 60079-0.  Instructions and safety precautions must be read and understood prior to using this equipment.  Comply with appropriate local, state, and national codes governing ventilation, fire protection, operation maintenance, and housekeeping. Reference OSHA, NFPA-33, EN Norms and your insurance company requirements.

AREA	HAZARD	SAFEGUARDS
Tells where hazards may occur.	Tells what the hazard is.	Tells how to avoid the hazard.
Spray Area / High Voltage Equipment	Electrical Discharge  There is a high voltage device that can induce an electrical charge on ungrounded objects which is capable of igniting coating materials.  Inadequate grounding will cause a spark hazard. A spark can ignite many coating materials and cause a fire or explosion.	Parts being sprayed and operators in the spray area must be properly grounded.  Parts being sprayed must be supported on conveyors or hangers that are properly grounded. The resistance between the part and earth ground must not exceed 1 meg ohm. (Refer to NFPA-33, EN 50176).  Operators must be grounded. Rubber soled insulating shoes should not be worn. Grounding straps on wrists or legs may be used to assure adequate ground contact.
		Operators must not be wearing or carrying any ungrounded metal objects.  When using an electrostatic handgun, operators must assure contact with the handle of the applicator via conductive gloves or gloves with the palm section cut out.  NOTE: REFER TO NFPA-33 OR SPECIFIC COUNTRY SAFETY CODES REGARDING PROPER OPERATOR GROUNDING.  All electrically conductive objects in the spray area, with the exception of those objects required by the process to be at high voltage, must be grounded. Grounded conductive flooring must be provided in the spray area.  Always turn off the power supply prior to flushing, cleaning, or working on spray
		Unless specifically approved for use in hazardous locations, all electrical equipment must be located outside Class I or II, Division 1 or 2 hazardous areas, in accordance with NFPA-33.



AREA	HAZARD	SAFEGUARDS
Tells where hazards may occur.	Tells what the hazard is.	Tells how to avoid the hazard.
Electrical Equipment	Electrical Discharge	
	High voltage equipment is utilized in the process. Arcing in the vicinity of flammable or combustible materials may occur. Personnel are exposed to high voltage during	Unless specifically approved for use in hazardous locations, the power supply, control cabinet, and all other electrical equipment must be located outside Class I or II, Division 1 and 2 hazardous areas in accordance with NFPA-33 and EN 50176.
	operation and maintenance.  Protection against inadvertent	Turn the power supply OFF before working on the equipment.
	arcing that may cause a fire or explosion is lost if safety circuits are disabled during operation.	Test only in areas free of flammable or combustible material.
	Frequent power supply shut-down indicates a problem in the system which	Testing may require high voltage to be on, but only as instructed.
	requires correction.	Production should never be done with the safety circuits disabled.
	An electrical arc can ignite coating materials and cause a fire or explosion.	Before turning the high voltage on, make sure no objects are within the sparking distance.
Toxic Substances	Certain material may be harmful if inhaled, or if there is contact with the skin.	Follow the requirements of the Material Safety Data Sheet supplied by coating material manufacturer.
A		Adequate exhaust must be provided to keep the air free of accumulations of toxic materials.
		Use a mask or respirator whenever there is a chance of inhaling sprayed materials. The mask must be compatible with the material being sprayed and its concentration. Equipment must be as prescribed by an industrial hygienist or safety expert, and be NIOSH approved.
Spray Area	Explosion Hazard – Incompatible Materials	
	Halogenated hydrocarbon solvents for example: methylene chloride and 1,1,1,-Trichloroethane are not chemically compatible with the aluminum that might be used in many system components. The chemical reaction caused by these solvents reacting with aluminum can become violent and lead to an	Aluminum is widely used in other spray application equipment - such as material pumps, regulators, triggering valves, etc. Halogenated hydrocarbon solvents must never be used with aluminum equipment during spraying, flushing, or cleaning. Read the label or data sheet for the material you intend to spray. If in doubt as to whether or not a coating or cleaning material is compatible, contact your coating supplier. Any other type of solvent may be used with aluminum equipment.

SI-04-02.8 **5** 

equipment explosion.

## INTRODUCTION

#### DESCRIPTION

The deuce cart is a self contained unit on wheels and can be transported and used in remote areas. It is a portable way to supply material and store the No. 2 process handgun all in one unit. It is commonly used at jobsite locations, such as offices, hospitals, painting contractors, job shops, and industrial finishing painter maintenance markets. Its uses include lockers, bathroom stalls, machinery, fencing, ornamental iron, playground equipment, steel doors and frames, patio furniture,

window extrusions, guard railings, steel roofing, conductive glass coatings, farm implements, snow plow equipment, water piping, etc. It is meant for use with solvent based coatings only. Oil industrial enamels, or alkyd oil based enamels, 2k and 1k epoxies and urethanes with resistivity range of .1 to 1 meg ohms are common materials. It has a ASME coded pressure tank and air compressor and foam filled tires included with the package.

79297 DEUCE CART PACKAGE OPTIONS			
Part #	Description		
79297-01	No. 2 Handgun w/Power Supply (Includes 25 Ft. Cable & Hose), Cart Assembly		
79297-02	No. 2 Handgun w/Power Supply (Includes 36 Ft. Cable & Hose), Cart Assembly		
79297-03	No. 2 Handgun w/Power Supply (Includes 25 Ft. Cable & Hose), Cart Assembly, 76708-00 Performance Package*		
79297-04	No. 2 Handgun w/Power Supply (Includes 36 Ft. Cable & Hose), Cart Assembly, 76708-00 Performance Package*		

<sup>\* 76708-00</sup> Performance Package includes: (2) Brush Assemblies, (5) Spray Gun Covers, (1) 4-inch Bell Assembly, (3) 4-inch Feed Tube Assemblies

#### NOTE

- ➤ This literature contains parts lists and figures that identify component parts of the 80002 Cart Assembly which is comprised of the following additional assemblies: 80001 Air Compressor Assembly and 79281 Pressure Pot Assembly.
- ➤ This document does not cover parts associated with the 19372 No. 2 Handgun Unit (Gun & Power Supply) or the 80001 Air Compressor. For further information on these units, refer to literature associated with that particular equipment.

## **INSTALLATION**

# POWER SUPPLY MOUNTING INSTRUCTIONS:

1. Assemble U-Brackets around power supply as shown. Tighten all bolts securely adjust to appropriate angle to achieve best viewing of the power supply display based on application" and reword the first part by adding in "tighten two bolts top and bottom to secure power supply.

#### **NOTE**

➤ Follow instruction for assembly of power supply see figure 4.




Figure 4: Diagram - Mounting Power Supply to Cart

## **OPERATION**

#### INSTRUCTIONS

 Fill the pressure pot with appropriate fluid. Tighten the lid properly to seal pressure. Adjust the pressure pot regulator to a small amount of pressure to insure the bell of the No. 2 process will not be flooded.

## **MARNING**

- ➤ The power supply and compressor must be located a minimum of 20' (6.8m) from the target being sprayed. This distance insures safe operation of the unit.
- 2. Plug in to 110/120 V outlet the power supply and the compressor power.
- 3. Turn the power supply on.
- 4. On a test panel, trigger the No. 2 process gun and adjust the pressure pot regulator till the proper pattern is generated.
- 5. Once the pattern size and flow rate is determined, spray the grounded target using techniques listed in the application manual.

# PARTS IDENTIFICATION




Figure 1: 80002 Cart Assembly



80002 CART ASSEMBLY - PARTS LIST (Figure 1)			
Item #	Description	Part #	Qty
1	Two-Wheel Cart Assembly	79989-00	1
2	Air Compressor	80001	1
3	PT Code Pressure Tank Assembly (Zinc Plated)	79281-00	1
4	Bracket Arm	80162-00*	2
5	U-Bracket	80163-00*	2
6	.25" x 1" Washer	71211-01*	12
7	Knob	80164-00*	2
8	1/4-20 Serrated Flange Bolt	AC-3710*	6
9	1/4-20 Serrated Flange Nut	AC-3903*	6
10	Single Gang Outlet Box	79287-00	1
11	Receptacle Electric GFCI 15 AMPS	79290-00	1
12	Water Proof Cover, Outer	79285-02	1
13	Water Proof Cover Gasket	79285-01	1
14	Grounding Wire Assembly 18"	79292-00	1
15	Flat Washer 1/4	55-6505-CD	2
16	Lockwasher Ext Tooth 1/4	7567-05	1
17	Pan Head Screw 1/4-20 x 1/2	20-202	5
18	Holster with Label, Deuce Cart	79458-00	1
19	Bolt Hex M8-1.25 x 50MM ZN PLTD	80371-00	4
20	Washer Flat M8 ZN PLTD	80372-00	4
21	Lock Washer M8 Split ZN PLTD	80370-00	4
22	Tee 1/4 NPT	3364-02	1
23	Hex Nipple 1/4 NPT	8115-01	2
24	Elbow 1/4 NPT	79332-00	1
25	Coalescing Filter	79987-00	1
26	Ball Valve	VA-542	1
27	Air Hose Assembly	HA-57030	1
28	Electrical Cord 14/3, 300V	79293-25	1
29	Electrical Plug NEMA 5-15, 15 AMPS	79291-00	1
30	Connector Strain Relief Line Cord	79288-00	1
31	Spade Terminal 16-14 AWG #10	79294-00	1
32	Grounding Wire Assembly 14"	79295-00	1
33	Deuce Cart Bracket Kit Assembly	80165-00	*=Included in Kit




Figure 2: 80001 Air Compressor Assembly

80001 AIR COMPRESSOR ASSEMBLY - PARTS LIST			
Item #	Description	Part #	Qty
1	Air Compressor	79988-00	1
2	Q.D. Air Fitting	Reference	Reference
3	Tee 1/4 NPT	3364-02	1
4	Hex Nipple 1/4 NPT	8115-01	2
5	Elbow 1/4 NPT	79332-00	1
6	Coalescing Filter	79987-00	1
7	Ball Valve	VA-542	1




Figure 3: 79281 Pressure Pot Assembly

79281 PRESSURE POT ASSEMBLY - PARTS LIST (Figure 3)			
Item #	Description	Part #	Qty
1	Pressure Pot	83C-210	1
2	St. Elbow, 3/8 NPT	SSP-1939	1
3	Ball Valve, 3/8 NPT(M) x 3/8 NPS(M)	VA-527	1
4	Nipple, Hex, 1/4 NPT(M)	SSP-462-ZN	1
5	Valve, Safety, 40 PSI	TIA 4040	1
6	Valve, Drain	SS-2707	1
7	Cross, 1/4 NPT(F)	SSP-3301-NI	1
8	Adapter, Swivel, 1/4 NPT(M) x 1/4 NPS(F)	SSP-8217-2	1
10	Male Branch Tee, 1/4 NPT(F)	SSP-2629-ZN	1
11	Bushing, 1/4 NPT(F) x 3/8 NPT(M)	20-1753-1	1
12	Gauge, Pressure 0-30 PSI, 2-1/2", 1/4 NPT(M)	83-1414	1
13	Regulator, Air 3/8 NPT(F)	HAR-501	1
14	Elbow, 1/4 NPT(F)	20-2848	1
15	Adapter, 1/4 NPT(M) x 1/4 NPS(M)	H-2008	1
16	Lid	PT-422	1
17	Nipple, 3/8 NPT(M) x 1/4 NPT(M)	83-4233	1
18	Fluid Tube	QMS-9-1	1
19	Gasket	PT-33-1	1
20	Tank Liner (Not Shown)	PT-78-K10	Sold in Packs of 10 & 60

## WARRANTY POLICIES

#### LIMITED WARRANTY

Ransburg will replace or repair without charge any part and/or equipment that falls within the specified time (see below) because of faulty workmanship or material, provided that the equipment has been used and maintained in accordance with Ransburg's written safety and operating instructions, and has been used under normal operating conditions. Normal wear items are excluded.

THE USE OF OTHER THAN RANSBURG APPROVED PARTS, VOID ALL WARRANTIES.

#### **SPARE PARTS:**

One hundred and eighty (180) days from date of purchase, except for rebuilt parts (any part number ending in "R") for which the warranty period is ninety (90) days.

#### **EQUIPMENT:**

When purchased as a complete unit, (i.e., guns, power supplies, control units, etc.), is one (1) year from date of purchase. WRAPPING THE APPLICATOR IN PLASTIC, SHRINK-WRAP, ETC., WILL VOID THIS WARRANTY.

RANSBURG'S ONLY OBLIGATION UNDER THIS WARRANTY IS TO REPLACE PARTS THAT HAVE FAILED BECAUSE OF FAULTY WORKMANSHIP OR MATERIALS. THEREARENOIMPLIED WARRANTIES NOR WARRANTIES OF EITHER MERCHANT ABILITY OR FITNESS FOR A PARTICULAR PURPOSE. RANSBURG ASSUMES NO LIABILITY FOR INJURY, DAMAGE TO PROPERTY OR FOR CONSEQUENTIAL DAMAGES FOR LOSS OF GOODWILL OR PRODUCTION OR INCOME, WHICH RESULT FROM USE OR MISUSE OF THE EQUIPMENT BY PURCHASER OR OTHERS.

#### **EXCLUSIONS:**

If, in Ransburg's opinion the warranty item in question, or other items damaged by this part was improperly installed, operated or maintained, Ransburg will assume no responsibility for repair or replacement of the item or items. The purchaser, therefore will assume all responsibility for any cost of repair or replacement and service related costs if applicable.



## MANUAL SUMMARY CHANGE

SI-04-02.8 replaces Service Manual SI-04-02.7, with the following changes:

- 1. New drawing (Cover).
- 2. Added No. 2 Handgun and Power Supply manuals numbers (Cover).
- 3. Changed model number of the Deuce Cart (Cover).
- 4. Update safety information (Page 2).
- 5. New description copy (Page 6).
- 6. Update Note (Page 6).
- 7. Enhanced explanation of power supply bracket assembly (Page 7).
- 8. Add "Operation" section (Page 8).
- 9. New "Parts Identification" drawing (Page 9).

#### Manufacturing

1910 North Wayne Street Angola, Indiana 46703-9100 Telephone: 260-665-8800

Fax: 260-665-8516

#### **Technical Service** — Assistance

320 Phillips Ave.

Toledo, Ohio 43612-1493

Telephone (toll free): 800-233-3366

Fax: 419-470-2233

Technical Support Representative will direct you to the appropriate telephone number for ordering Spare Parts.